



SERVICE BULLETIN



SERVICE DEPARTMENT... CHRYSLER-PLYMOUTH DIVISION
CHRYSLER MOTORS CORPORATION

TECHNICAL INFORMATION ON IMPERIAL CHRYSLER PLYMOUTH VALIANT

March 29, 1963

No. 63-71

In order to insure against the possibility of objectional detonation in 1963 Chrysler 300J model engines, the basic ignition timing was changed to 12-1/2^o B.T.C.

This change should be made on any C-300J models in dealer inventory and on any C-300J model brought in for service.

Please make notation of the new specification in your Chrysler-Plymouth Service Bulletin No. 63-34, dated December 26, 1962.

The new basic ignition timing of 12-1/2^o B.T.C. began with engine date code 3-1-62. Refer to Chrysler-Plymouth Service Bulletin No. 63-1A, dated December 19, 1962.

POLICY: INFORMATION ONLY.

ELECTRICAL

BASIC
IGNITION
TIMING

J. W. FARLEY
Manager-Service
CHRYSLER-PLYMOUTH DIVISION

1963
CHRYSLER
300J
MODELS

P-1298-C

Service Mgr.	
Shop Foreman	
Technicians	
Parts Mgr.	
Partsmen	